Survey No. SM-372

## Maryland Historical Trust State Historic Sites Inventory Form

Magi No. 1902723704

DOE \_\_yes \_x no

1. Nam	e (indicate pre	eferred name)		
historic	MATTINGLY HOU	SE		
and/or common				
2. Loca	ation			
street & number	E, Side Old R		north of Charlot hool Road	te _ not for publication
city, town	Charlotte Hal	1 vicinity of	congressional district	
state	Maryland	county	St. Mary's	
3. Clas	sification			
Category  district building(s) structure site object	Ownership  X public  private  both  Public Acquisition  in process  being considered  not applicable	Status occupied _X_ unoccupied work in progress Accessible _X_ yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation cother: vacant
name M	aryland Veterans 11 Bladen S 01d Armory	treet	telephone no	.:
city, town	Annapolis	state :		land 21401
		al Descriptio		
•		t. Mary's County		liber
street & number	·····			folio
city, town L	eonardtown		state	Maryland
6. Rep	resentation	in Existing	Historical Surve	ys
tle	- · · · · ·			
date			federalstate	county loca
depository for su	rvey records			
city, town			state	

Condition excellent	X_ deteriorated	Check one unaltered	Check one	eita	
			•		
good	ruins	<u> </u>	X moved	<b>date</b> of move	
fair	unexposed				

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

7. Description

The Mattingly House stands on the east side of Old Route 5, between the Davis House (SM-371) and the IRS Building (SM-373) in Charlotte Hall, Maryland.

Survey No.

SM - 372

The Mattingly House is a two story, four bay wide gable-roofed house with a double cross gable on the west or entrance facade. A wide one story hipped-roof screened porch extends across the west facade, with entrances on the west, north and south sides.

The entrance doors, one below each of the cross gables, are made of beaded flush paneling. The windows on the north, west, and south facades are mostly 2/2 double hung windows. A six bay wide two bay deep shed roofed wing and an adjoining one story two bay gable roofed wing extend from the east elevation. This section is probably much later than the main block and the windows are mostly paired or triple 6/6 sash. There is a small one story shed-roofed addition on the northeast corner of the house with an entrance on the east facade.

The interior plan is the product of several alterations and is unusual in that circulation along the entire length of the There is a stairway house is only possible on the second floor. at both the north and south ends of the house. Underneath the plaster wall of the south stair there is evidence of hand-split lathing, suggesting that this may be the oldest section of the house. The thick wall separating this section from the gable roofed east addition also suggests a number of different building periods and that the addition was possibly moved there from another location. Another unusual feature of the interior is the There is litcove ceiling of the south room on the second floor. tle original woodwork or moulding on either floor and most of the walls are covered with thin plywood paneling.

0. 3	rigililicalice		Survey No.	SM-3/2
#riod 	2—1499 archeology-historic 2—1599 agriculture 2—1699 x architecture 2—1799 art 2—1899 commerce	community planning	law literature mllitary music	science sculpture social/ humanitarian theater
Specific	dates	Builder/Architect		
check:	Applicable Criteria:A and/or Applicable Exception:		E F G	
	Level of Significance:		<del></del>	
Prepare	both a summary paragraph	of significance and	a general statement	of history and

Cianificance

Prepare both a summary paragraph of significance and a general statement of history and support.

The Mattingly House, despite its late nineteenth century appearance, is probably the product of several different building periods, and is undoubtedly the oldest of the three homes once owned by Charlotte Hall School on the east side of Old Route 5 in Charlotte Hall. The use of hand-split lathing in the south stairway and the beaded flush paneling of the two doors are characteristic of the second quarter of the nineteenth century. The thick wall separating the east addition from the rest of the house suggests that the addition was moved from another part of the property and attached to the house. Most of the interior has been greatly altered, however, and most of the mid-century woodwork and moldings no longer exist. The floor plan of the original house has also been obscured.

Land Records, St. Mary's County

10. Ge	ographical Dat	а			
Acreage of nom Quadrangle nam UTM References			•	Quadrangle scale	Charlotte Hall
A Zone East	ing Northing	B   2	one Easting	Northi	ng l
C		] D			
Verbal bounda	ary description and justification	on			
	and counties for properties o		or county bo		
state state	code	county	:	code	
11. Fo	rm Prepared By	7	4		
name/title	Geoffrey Henry		<del></del>		
organization	Maryland Historical	Trust	date		
street & number	21 State Circle		telephone	269-2438	
city or town	Annapolis		state	Maryland	21401

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:


Maryland Historical Trust


Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438







SM - 372

Mattingly House

W. Facade

Charlotte Hall, Maryland

Geoffrey Henry 7/84

Negatives at Maryland Historical Trust



SM - 372 Mattingly House Charlotte Hall, Maryland

Geoffrey Henry 7/84 Negatives at Maryland Historical Trust

East Facade



Davis House Charlotte Hall, Maryland South Facade

SM - 372

Geoffrey Henry 7/84 Negatives at Maryland Historical Trust



NE Corner

SM - 372

Charlotte Hall, Maryland

Geoffrey Henry 7/84

Mattingly House

Negatives at Maryland Historical Trust



SM - 372 Mattingly House Charlotte Hall, Maryland SE Corner

Geoffrey Henry 7/84 Negatives at Maryland Historical Trust



SM-372 Mattingley House Charlotte Hall, Md. West elevation Geoffrey Henry Negatives at MHT

7/84